NAPA ®

PRODUCT QUALITY BULLETIN

NAPA Gold 3678: Design Error

NAPA Gold Fuel Filter	Total Quantity Shipped:	Affected Date Codes:
3678	575 Units	25MHM06 11767 25MHM21 11767 25MEJ06 11767

ISSUE SUMMARY:

A design error in the filter cap prevents the filter from fitting properly into the housing. As a result, the filter cannot be locked in place, which allows fluid to leak from the housing.

REQUIRED ACTION:

Please dispose of the part and submit a request for VDM credit.

QUESTIONS OR ASSISTANCE:

If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.