



# PRODUCT QUALITY BULLETIN

#481

**NAPA Air Filter 2769:  
Incorrect seal placement**

NAPA Air Filter	Total Quantity Shipped:	Affected Date Codes:
2769	93 Units	24MYUJ10 9927

**ISSUE SUMMARY:**

Incorrect seal placement on filter.

**REQUIRED ACTION:**

1) Please dispose of the part and contact your local representative to follow the standard credit process.

**QUESTIONS OR ASSISTANCE:**

If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.

