



WRONG FILTER NOTICE

#483

NAPA Gold 3037:
Incorrect Filter in the box.

AFFECTED PRODUCT:

- It was previously identified that some NAPA 3037 fuel filters have been incorrectly packaged with a 308439 canister-style fuel filter inside the box.
- The 308439 filter is not a suitable replacement for the 3037 and may result in improper fitment or performance issues if installed.
- A total of 2280 filters mix-boxed between 2021 and 2023.
- The permanent corrective action was implemented on 4/18/2024.

ACTION REQUIRED:

1. Check all stock of NAPA 3037 filters for the affected date code 23MRS21 9616 printed on the packaging.
2. If Affected Product Is Found:
 - Do NOT sell or install the product.
 - Request credit through the standard return process.
 - Destroy the product after credit is issued to prevent accidental use.

Part Number on Box:	Incorrect Product Found Inside:	Affected Date Codes:
NAPA 3037 (Cartridge Style Fuel Filter)	308439 (Canister Style Fuel Filter)	060722 23MTA11 9616 23MRS21 9616

