



## PRODUCT QUALITY BULLETIN

#496

**NAPA Cabin Air Filter 9979:**  
Filter design error

<b>NAPA Cabin Air Filter</b>	<b>Total Quantity Shipped:</b>	<b>Affected Date Codes:</b>
<b>9979</b>	<b>362 Units</b>	<b>24MYM20 9927 24MYUJ10 9927</b>

### ISSUE SUMMARY:

Air flow arrows are incorrect with a thickness issue preventing installation.

### REQUIRED ACTION:

1) Please dispose of the part and contact your local representative to follow the standard credit process.

### QUESTIONS OR ASSISTANCE:

If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.

