



PRODUCT BULLETIN

#548

NAPA Gold 3002:
Loose internal component

AFFECTED PRODUCT:

- It was previously identified that some NAPA 3002 fuel filters have loose media pack element from manufacturing date 25MYM22. Products from this date should be considered suspect and removed from stock.

ACTION REQUIRED:

1. Check all stock of NAPA 3002 filters for the affected date code 25MYM22 10300 printed on the filter.
2. If Affected Product Is Found:
 - Do NOT sell or install the product.
 - Request credit through the standard return process.
 - Destroy the product after credit is issued to prevent accidental use.

NAPA Fuel Filter:	Affected Date Codes:
3002	25MYM22 10300

