



WRONG FILTER NOTICE

#552

NAPA Gold Fuel Filter 3705:
Incorrect Filter in the box.

AFFECTED PRODUCT:

- It was previously identified that some NAPA 3705 metal filters have been incorrectly packaged with a NAPA 3085 plastic filter inside the box.
- The 3085 filter is not a suitable replacement for the 3705 and cannot be installed.
- A total of 200 pieces were mix-boxed.

ACTION REQUIRED:

1. Check all stock of NAPA 3705 for a metal style filter.
2. If Affected Product Is Found:
 - Do NOT sell or install the product.
 - Request credit through the standard return process.
 - Destroy the product after credit is issued to prevent accidental use.

Part Number on Box:	Incorrect Product Found Inside:	Affected Date Codes:
NAPA 3705 (Metal Fuel Filter)	NAPA 3085 (Plastic Fuel Filter)	ALL

