



PRODUCT QUALITY BULLETIN

#557

NAPA Air Filter 6829:
Filter design error

NAPA Air Filter	Total Quantity Shipped:	Affected Date Codes:
6829	207 Units	24MYUJ10 9927

ISSUE SUMMARY:

Filter will not install into housing sleeve.

REQUIRED ACTION:

If this issue is identified on your part, please dispose of the part and contact your local representative to initiate the standard credit procedure.

QUESTIONS OR ASSISTANCE:

If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.

