



## PACKING ERROR NOTICE

397

**NAPA Gold 9660:**  
Incorrect filter in package.

The following item was shipped with an incorrect filter in the box.

Please inspect your inventory for the part number listed below.

If incorrect filters are identified, please dispose of them and submit a request for VDM credit.

Incorrect quantity: 252

**INCORRECT FILTER**  
(Spin-On Fuel)



**CORRECT FILTER**  
(Cylindrical Air)

