



## PRODUCT QUALITY BULLETIN

#545

**NAPA Air Filter 9205:**  
Filter design error

<b>NAPA Air Filter</b>	<b>Total Quantity Shipped:</b>	<b>Affected Date Codes:</b>
<b>9205</b>	<b>89 Units</b>	<b>24MYUJ10 9927</b>

**ISSUE SUMMARY:**

Filter design error not allowing the filter to install into the housing.

**REQUIRED ACTION:**

1) Please dispose of the part and contact your local representative to follow the standard credit process.

**QUESTIONS OR ASSISTANCE:**

If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.

