



PRODUCT QUALITY BULLETIN

#558

NAPA Air Filter 6562:
Filter design error

NAPA Air Filter	Total Quantity Shipped:	Affected Date Codes:
6562	2,913 Units	24MEJ20 8803 24MR015 8803

ISSUE SUMMARY:

Hard & excess material on the filters inner seal.

REQUIRED ACTION:

If this issue is identified on your part, please dispose of the part and contact your local representative to initiate the standard credit procedure.

QUESTIONS OR ASSISTANCE:

If you have any questions or need help coordinating the return, please contact our product support team.

We apologize for any inconvenience and appreciate your prompt attention to this matter.

