



WRONG FILTER NOTICE

#417

NAPA Gold 2404:
Incorrect Filter in the box.

- The following item was shipped incorrect filter in the box.
- Please inspect your inventory of part number 2404 for date code "24MLA08 9927", "24MLA15 9927" printed on the filter.
- Please dispose of the part and submit a request for VDM credit.
- Incorrect quantity shipped: 850

Part Number	Defective Date Code
2404	24MLA08 9927
	24MLA15 9927

Part Number	Issue – Dimensional Difference
2404	Correct Filter OD: 8.35 in, ID: 4.14 in
	Incorrect Filter OD: 9.01 in, ID: 4.37 in